

Accurate Energetic Systems, LLC

MATERIAL SAFETY DATA SHEET

BOOSTER, NON-ELECTRIC with PYX

MSDS NO. 1002.017

HAZARD RATING: **Health - 2** **Flammability - 3** **Reactivity - 4** **Special - High Explosive Component**

SECTION I - MANUFACTURE'S INFORMATION

Manufacture/Distributor Name: Accurate Energetic Systems, LLC
Address: 5891 Highway 230 West, McEwen, TN 37101
Telephone Number: (931) 729-4207
Emergency Telephone Number: 1-800-255-3924
Date Prepared: 04/20/01 **Supercedes:** 12/02/99

SECTION II - CHEMICAL COMPOSITION

Component	CAS #	%	OSHA PEL	ACGIH TLV	Other Limits
PYX (2,6-bis(picrylamino)-3,5-dinitropyridine)	38082-89-2	As required	n/a	n/a	n/a
Aluminum (metallic casing)	7429-90-5		15 mg/m ³ (total dust) 5 mg/m ³ (resp. fract) - metal dust - metal dust	10 mg/m ³ - metal dust	10 mg/m ³ (total dust) 5 mg/m ³ (resp. fract) - metal dust; NIOSH

NOTE: Hazard Class 1, Division 1; SCG "D"

NOTE: Materials in this product are subject to the reporting requirements of SARA, Title III, Section 313 as follows:
aluminum (fume or dust)

SECTION III - PHYSICAL AND CHEMICAL DATA (NOTE: Data is for PYX only except for "Appearance and Odor")

Boiling Point: n/a
Specific Gravity: 1.77
Melting Point: >370⁰C
Vapor Pressure (mm Hg): n/a
Vapor Density (Air = 1): n/a
Evaporation Rate (Butyl Acetate = 1): n/a
Solubility In Water: Insoluble
Appearance And Odor: Primarily cylindrical-shaped, open-ended aluminum cup with the explosive charge yellow in color. No distinguishing odor

SECTION IV - FIRE AND EXPLOSION HAZARDS

Flash Point: n/a

Flammable Limits: LEL n/a UEL n/a

Extinguishing Media: Water sprinkler or deluge system which is automatically activated.

Special Fire Fighting Procedures:

Do not attempt to fight fires involving high explosives. Isolate area and immediately evacuate all personnel from the area to a safe distance using as much protective cover as possible.

Unusual Fire And Explosion Hazards:

HIGH EXPLOSIVE!! The explosive is under confinement and may be caused to detonate by burning material surrounding the non-electric boosters. Metallic fragments are a secondary hazard.

SECTION V - REACTIVITY/COMPATIBILITY DATA

Stability:

Stable under normal conditions. High heat, shock, friction, impact, electrical discharge when supplied in sufficient energy can cause initiation of the non-electric boosters.

Incompatibility (materials to avoid):

Avoid oxidizers, alkalis and acids.

Hazardous Decomposition Products:

During decomposition, emits carbon dioxide, carbon monoxide, and oxides of nitrogen.

Hazardous Polymerization:

Will not occur

SECTION VI - HEALTH HAZARD DATA

NOTE: Under normal conditions of handling, personnel should not come in contact with the explosive material in the non-electric booster. The metallic casing should not pose a serious health threat except possibly through post-detonation fumes.

Routes Of Entry:

Eye?	Unlikely
Inhalation?	Yes (post-detonation fumes)
Skin?	Unlikely
Ingestion?	Unlikely

Effects Of Over-Exposure:

Acute -	Slight to serious effects
Chronic -	Not fully known

Signs And Symptoms Of Exposure:

PYX may cause nervous system irregularities including headaches and dizziness. Possible irritation of skin, eyes, and breathing tract. Through ingestion (depending on amount), may cause stomach upset, difficulties in digestion, possibly death.

Medical Conditions Generally Aggravated By Exposure:

Cardiovascular disease and glaucoma. Personnel should be in generally good health

SECTION VI - HEALTH HAZARD DATA (cont.)

Emergency First Aid Procedures:

- Eye -** Flush with water for 15 minutes. Remove contact lenses prior to flushing, if applicable. Get medical attention.
- Inhalation -** Remove to fresh air. Give oxygen if necessary. Get medical attention.
- Skin -** Wash with soap and warm water. Get medical attention for rash or irritation.
- Ingestion -** If conscious, drink large quantities of water and induce vomiting immediately. Contact a physician or Poison Control Center immediately.
- Other -** Accidental detonation may result in severe personal injury. Provide first aid as applicable and obtain medical attention immediately.

Carcinogenicity:

- NTP?** Not listed
- IARC Monographs?** Not listed
- OSHA Regulated?** Not listed

SECTION VII - PRECAUTIONS FOR SAFE HANDLING AND USE

Steps To Follow If Material Is Spilled Or Released:

If explosive material is spilled from metallic casing, remove all sources of ignition. Avoid any and all situations which could initiate the material, such as friction, impact, heat, sparks, or electrostatic discharge. Wet down material with water. Sweep up spill with a soft bristle brush and a non-sparking pan or shovel. Place material in a properly labeled storage container and store in an approved storage magazine for further disposition.

Waste Disposal Method:

Dispose of in accordance with applicable local, state, and federal regulations.

Precautions To Be Taken In Handling And Storage:

Handle with care. Store only in authorized High Explosives magazine with compatible material and away from all sources of ignition and flammable materials. Do not store with detonators, initiating (Primary) explosives, flammable liquids or solvents.

Other Precautions:

The non-electric boosters are generally considered UNO Class 1.1 hazardous material and the storage compatibility group (SCG) is "D".

SECTION VIII - PERSONAL PROTECTION INFORMATION

Respirator Protection (Specify Type):

Under normal handling, none required.

Ventilation:

- Local Exhaust -** Under normal handling, none required.
- Mechanical (General) -** Under normal handling, none required.
- Special -** n/a
- Other -** n/a

Protective Gloves:

Under normal handling, none required.

Eye Protection:

Safety glasses or goggles that meet or exceed ANSI Z87.1 (latest revision)

Other Protective Clothing Or Equipment:

Cotton clothing recommended. Hearing protection should be worn when detonating non-electric boosters.

Work/Hygienic Practices:

Wash hands thoroughly after handling.

SECTION IX - SPECIAL PRECAUTIONS

Precautions To Be Taken:

CAUTION: High explosives are extremely dangerous. When detonated, high velocity metallic fragments are generated. Non-electric boosters must be handled only by qualified personnel who are experienced and highly trained in the use of and familiar with the hazards inherent in explosives. When non-electric boosters are detonated or destructively tested, all personnel must be protected from the effects of blast overpressure and fragments. Allow the post detonation fumes and dust to clear before entering the area. Follow all safety regulations and precautions when handling, storing, or processing explosive material.

The information contained herein is believed to be accurate and represents the best information currently available. Accurate Energetic Systems, LLC makes no warranties or guarantees with respect to the safety or suitability of this product or the results obtained, either expressed or implied. Buyer and user assume any and all risk, responsibility, and liability for any and all injury (including death), loss, or damage arising from usage.